


Plasma Cutting Torch • PT Series



Model: PT-60

Current: 10-60A • Duty Cycle: 60A @ 80% • EN60974-7 • Gas: Air / N2 • Gas Pressure: 65-75 psi (4.4-5.0 Bar) • Gas Flow: 230scfh (110 lpm)



Torch Package

Code	Description
09637/LG	6m Cable Central Connection

Main Consumables & Spare Parts

Code	Description	Pack Qty
1	09603 PT60 Torch Head	1
1A	51620.60 'O' Ring	5
2	09605 Handle c/w Switch	1
3	52582 Electrode - Back Striking	5
4	60028 Gas Distributor	1
5	51313P.10 Flat Cutting Tip 1.0 40-50A Back Striking	10
	51313P.11 Flat Cutting Tip 1.1 50-60A Back Striking	10
6	51318.06 Tip Contact Cutting 0.65 10-20A Back Striking	10
	51318.08 Tip Contact Cutting 0.8 20-30A Back Striking	10

Main Consumables & Spare Parts (continued)

Code	Description	Pack Qty
7	51312P.09 Tip Contact Cutting 0.9 30-40A Back Striking	10
8	52583 Extended Electrode Back Striking	5
9	51318L.06 Extended Tip Contact Cutting 0.65 10-20A Back Striking	10
	51318L.08 Extended Tip Contact Cutting 0.8 20-30A Back Striking	10
10	51314.09 Extended Tip Contact Cutting 0.9 30-40A Back Striking	10
11	60389 Retaining Cap 6 Holes	1
12	60432 Double Pointed Spacer (For use with items 5 & 6 Only)	1
13	51866 Circle Cutting Attachment (Not Illustrated)	1